

Cold Engine Starts

- The following are some important items to consider when a machine is started in cold conditions:
 - 1. Ensure your glow plugs are working properly by using the glow plug testing procedure outlined in the machine repair manual
 - 2. Turn key counter clockwise to activate glow plugs and hold for approximately 15 seconds.
 - 3. Do not crank the starter for more than 15 seconds, if engine fails to start, preheat engine again.
 - 4. Make sure you are using the proper manufacture-specified engine oil and hydraulic oil
 - 5. Idle your machine for approximately 5 minutes before actual use
 - 6. Some helpful options available for your Thomas loader are block heaters, plugged in approximately 2 hours before use, as well as hydraulic tank and fuel line heaters (available in certain models).